



## INFORMATION BULLETIN

No. M 462-RF/20

**COVERS :** Detachment and refitting of MN 14-B oil pumps on M 462-RF engines.

**REASON :** Some operators reported defects of MN-14 B oil pump driving shafts.

**MEASURE:** In order to prevent oil pump driving shaft defects, measures must be taken during fitting of MN-14 B oil pumps on M 462-RF engines, to provide its smooth turning. Smooth turning of the driving shaft can be checked on the removed complete rear drive box. This means, that the oil pump should be fitted to the removed rear drive box and smooth turn checked by turning the slotted shaft powering the agricultural implements.

In case of necessary replacement of the oil pump, the manufacturers in view of complicated operation of this replacement suggest the engine users to order carrying-out of this replacement at the manufacturer's service department or, to delegate the fitters or servicing engineers for proper instructional training in this line to the manufacturer's servicing center.

Praha 9 - Letňany, October, 27, 1972.

M. Adamec m.p.

.....  
Manufacturers' Representative

Ing. B. Homola m.p.

.....  
Customer's Representative  
at Manufacturers' Works

Ing. M. Kohout m.p.

.....  
State Aviation Inspection

Ing. J. Pavlovský m.p.

.....  
OMNIPOL