



**LOM PRAHA**  
s.p.



**MANDATORY BULLETIN**

**#**

**M337AK.1/7a**

*Scope:* M337AK.1 engine ser.no. 7961054, 7961055, 11961001, 11961002 stored by the Czech military forces for reserve.

*Justification:* Carrying out the same provisions on the above mentioned reserve engines as had been carried out with the engines in service. Replace Petroflex rubber hoses for Tuboflex metal hoses.

*Provisions:* If it is necessary to mount the above mentioned engines in ZLIN 142CAF aircraft contact LOM PRAHA s.p. service to replace the rubber hoses for the current ones prior to mounting the engine in the aircraft as in the drawings number Sc0625, Sh0624, 6x470 CSN137821.3 standard and 6x200CSN137821.3standard.

Upon reception of this bulletin the VU2553 Pardubice base shall mark appropriately the engine books and boxes of the above mentioned engines with the following warning:

“Prior to mounting the engine into aircraft, carry out the provisions under bulletin M337AK.1/7a.”

If the engines life cycles were before expiration of the preservation period and not intended to mount into aircraft, it is recommended to send the engines as soon as possible to represervation and hose-replacement to LOM PRAHA s.p.

*Responsible for carrying out:* LOM PRAHA s.p. as requested in customer's order

*Material:* supplied by LOM PRAHA s.p.

*Cost:* cost related to hose replacement (material, labour) to be born by LOM PRAHA s.p.

*Validity:* on the date of bulletin reception

*Given in Prague on 22/06/1998*

Maj. Ing. Miroslav Siuda  
Mil Rep to LOM PRAHA s.p.

Ing. Vladimír Zasadil, CSc.  
Director, LOM PRAHA s.p.