

TISKAŘSKÁ 8, 100 38 PRAHA 10, CZECH REPUBLIC

SERVICE LETTER No.:

0012/2009

Ref.: Engines M337, M332, M137 and M132 of all versions that had extended operating periods up to the complete overhaul by the firm W-MOTOR SERVICE, s.r.o. after February 2006.

Reason: Additional survey to the mandatory bulletin No. LOM-MB-03a/2009. It is necessary to find out if the list of the engines specified in the bulletin No. LOM-MB-03a/2009 is complete or there are other engines, extended in this way, outside this register. This action was initiated and is followed by ÚCL-ČR.

Measure: We ask users of the above to check records in the engine books for extension of operating periods. The engines with operating periods extended by the firm W-MOTOR SERVICE, s.r.o. after February 2006 shall be reported to LOM PRAHA s.p. Use the form on page 2 of this Service letter for reporting. Complete and scan the form and send to the contact email: piston.engines@lompraha.cz as soon as possible, however at the latest by November 16, 2009.

Caution: All engines extended by the firm W-MOTOR SERVICE, s.r.o. after February 2006 will be considered to be air unworthy unless they are checked additionally according to the bulletin LOM-MB-03a/2009 and acknowledged as airworthy.

Validity: From the approval day.

In Prague on: 12. 8. 2009 Approved according to the authority of DOA č.
EASA.21J.306.

Approved by:

Ing. Petr Prokop, MBA, m. p.
Manager of Design Organisation

Dotazník k servisnímu dopisu LOM PRAHA s.p. č. 0012/2009.
Answer Sheet to Service Letter LOM PRAHA s.p. No. 0012/2009.

Typ motoru <i>Engine type</i>		
Výrobní číslo motoru <i>Engine serial number</i>		
Rok výroby motoru <i>Year of engine manufacturing</i>		
Datum poslední GO motoru u firmy <i>Date of the last overhaul performed at Company .</i>		
Celkový počet hodin <i>Total time since new - TTSN</i>		
Provozní doba od poslední GO <i>Time since overhaul - TSO</i>		
Druh prodloužení provozní lhůty <i>Type of TBO extension</i>	Kalendářně *) <i>Calendar *)</i>	Hodinově *) <i>Hour rate*)</i>
Datum prodloužení provozní lhůty <i>Date of TBO extension</i>		
Prodloužení provedl <i>The extension executed by</i>		
Spolehlivost motoru po prodloužení TBO. Odstraněné závady. <i>Engine reliability after TBO extension. Troubleshoot performed.</i>		

*) zaškrtněte/mark

Při nedostatku místa pokračujte na druhé straně. / If it is necessary – continuing on the reverse page.

Prohlášení:

Provozní lhůta motoru byla prodloužena firmou W-MOTOR SERVICE, s.r.o. po únoru 2006.

Declaration:

TBO of engine was extend by firm W-MOTOR SERVICE Ltd.(s.r.o.) after february 2006.

Datum/Date:

Organizace/Establishment:

Podpis/Signature:

.....

.....

.....