



SERVICE LETTER No.: 0008 / 2007

Relates to : The M337C engines of Serial Nos.: 159021072 and 15971068 and other LOM in-line inverted piston engines of the M337, M332, M137, M132 types in all versions.

Reason : Taking measures so that the identification data cannot be misused.
During transportation of two units of the M337C engines of above mentioned Serial Numbers the identification labels and engine log books have been stolen.
Through this the principles pursuant to the EASA PART 21A.803 regulations have been infringed.
Information for aviation publicity.

Measures : All above mentioned engines marked by the stolen identification labels M337C with Serial Numbers 159021072 and 15971068 are not airworthy.
The Serial Numbers 159021072 and 15971068 are invalid.
The M337C engine log books designated with Serial Numbers 159021072 or 15971068 are invalid.
Watch the Serial Numbers of LOM in-line inverted piston engines and of the engine log book during inspections, audits, matriculations, commercial transactions, leasing of engines, etc.

Measures to be executed by: National aviation authorities, owners, organisations authorised to perform maintenance, users, pilots and mechanics.

Costs : No cost will be incurred.

Validity : On the date of issue.

In Prague on: December 17, 2007

Approved based on DOA authorisation No. EASA.21J.306.

Approved by:

Ing. Petr Prokop, MBA, m.p.
Executive Manager of Design Organisation