



# LOM PRAHA s.p.

100 38 PRAHA 10 • 270 ČERNOKOSTELECKÁ STREET  
CZECH REPUBLIC

## SERVICE BULLETIN No. M337/94a

**Concerns :** The precision of marking of engine M337.

**Reason:** The certificate of marking of engine was issued for type M337.  
Producer of engine M337 Motorlet Praha equipped of engines M337 with unsuitable label of type with mark M337-Sh.

**Measure:** If there is on the engine label of type M337-Sh as matter of fact it is engine M337.

**a) Measure for users of engine M337.**

In case that marking M337-Sh is mentioned in Log Book of engine, please correct this name with refer to this bulletin.  
The label of engine is not necessary to correct neither to change.

**b) Measure for servicemen of engine M337.**

During performing of partial repair or overhaul arrange grinding out of label of type. We recommend to perform, when the upper cover of crankcase is taken off.

In case that marking M337-Sh is mentioned in Log Book of engine, please correct this name to M337 with refer to this bulletin.

**Note:** In speech and written utterance concerns to engine M337 use types mark M337 only.

**Measure will be executed:** Perform of correcting of Log Book - users and repairmen of engine M337.  
Perform of correcting label - repairmen of engine M337 during arrangement partial repair or overhaul of engine.

**Material:** It is not necessary.

**Costs:** They is not came.

**Validity:** Date of issue.

**Prague:** May 10, 2001.

Dipl. Ing. J. Pietrik, m.p.  
DAR

Dipl. Ing. V. Zasadil, CSc, m.p.  
Chief manager of LOM PRAHA s.p.