

### List of valid Service Letters of LOM PRAHA s.p. for Piston Engines and Propellers

	Date of issue:	Concerning:	Letter category:	Note:
<b>0001 / 2004</b>	March 15, 2004	Principles of mixing of engine oils for the aircraft piston engines of LOM PRAHA s.p. Oil changes entering into the engine logbook.	M	--
<b>0002 / 2004</b>	August 25, 2004	Cancellation of the M332/64 and M337/66 bulletins	M	--
<b>0003 / 2005</b>	March 30, 2005	Cancellation of the M337A/9b and M337AK/4b bulletins	M	--
<b>0004 / 2005</b>	May 25, 2005	Introduction of the ultrasonic flaw detection inspection of connecting rods at GO	O	--
<b>0005 / 2005</b>	September 12, 2005	Cancellation of bulletins	M	--
<b>0006 / 2006</b>	May 15, 2006	Introduction of the provision of the change service information on the web pages of LOM PRAHA s.p. - <a href="http://www.lompraha.cz">www.lompraha.cz</a>	M	--
<b>0007 / 2012 / R1</b>	July 4, 2012	Service Letter revision. Introduction of spark plugs L22.62A for the engines M132, M137, M332 and M337 of all versions.	M	--
<b>0008 / 2007</b>	December 17, 2007	During transportation of two units of the M337C engines S/N 159021072 and 15971068 the identification labels and engine log books have been stolen. Taking measures so that the identification data cannot be misused.	M	--
<b>0009/2009</b>	June 3, 2009	Announcement of persons authorized by LOM PRAHA s.p. to prolong the operational limits of the M337, M337A, M337AK, M137A, M137AZ engines under the valid information bulletins and to inspect the engines M337, M332, M137, M132 of all versions after 15 years of operation under the valid mandatory bulletin.	M	--
<b>0010/2009</b>	June 3, 2009	Information on the LOM ASSISTANCE system cancellation. Cancellation of the periodical inspection after 100 hours of operation or 12 months for the engines of model lines M337, M332, M137 and M132 of all versions maintained in the LOM ASSISTANCE system.	M	--
<b>0011/2009</b>	June 22, 2009	List of new documents issued during May and June 2009.	M	--
<b>0012/2009</b>	August 14, 2009	Additional survey to the mandatory bulletin No. LOM-MB 03a/2009. It is necessary to find out if the list of the engines specified in the bulletin No. LOM-MB-03a/2009 is complete or there are other engines, extended in this way, outside this register.	M	--

Last revision date: July 4, 2012