



# LOM PRAHA

100 38 PRAHA 10 - MALEŠICE • ČERNOKOSTELECKÁ 270

ČESKÁ REPUBLIKA

## SERVICE BULLETIN

No.: M337AK.1/3a

It is necessary to carry out!

Concern: Issue of a new independent "Technical description and maintenance manual for M337AK.1 engine".

Reason: Uniqueness of a service technical documentation with regard to the specific operation of M337AK.1 engines in Army of the Czech Republic (ACR).

Measures: 1. Introduction of a new service documentation for M337AK.1 engines  
By the March 17, 1997 there is issued new service documentation "TECHNICAL DESCRIPTION AND MAINTENANCE MANUAL FOR M337AK.1 ENGINE".  
From this date keep service instructions and maintenance procedures as per this service documentation.

2. Cancellation of original service documentation for M337AK.1 engines  
There is cancelled following original service documentation for M337AK.1 engines because of issue of a new service documentation for M337AK.1 engine:

- a) Technical description and maintenance manual for M332, M137/M337 engines of all versions;
- b) Supplement No. 1 to the Technical description and maintenance manual for M332, M137/M337 engines of all versions.

Will provide: A) LOM PRAHA - by securing of necessary number of a new service documentation copies and its registration.

- B) Holders of original service documentation for M337AK.1 engines:
- by ordering of a new service documentation and keeping of instructions stated in this documentation;
  - by sending back of original service documentation to LOM PRAHA.

Costs: No expenses will arise

Validity: March 17, 1997

Prague, February 21, 1997

Vladimír ZASADIL, ME  
Head of engine manufacturing

major Miroslav SIUDA, ME  
Head of customer relations