

**INFORMATION BULLETIN**

No. M 462-RF/11

**RE:** Utilization of standardized packings for mounting oil collectors of the M 462-RF engine.

**MOTIVE:** Front packing Part No. 14-702-07, and rear packing, Part No. 14-702-08 of the oil collector are supplied by the manufacturer of spare parts in two different thicknesses (1.5 mm and 2 mm) that are not differentiated by any marking from each other. The mounting of packings of different thickness and retightening the oil collector may somewhat contribute to flange cracking.

**PREVENTIVE MEASURE:**

In mounting the oil collector on the engine the front and the rear packing must have equal thickness.

Letňany, 28th August, 1969.

M. Adamec m. p.

.....  
Manufacturer's Representative

Ing. Homola m. p.

.....  
Customer's Representative

Langr m. p.

.....  
Supplier's Representative