



LOM PRAHA s.p.

Division of aviation piston engines

100 38 PRAHA 10 - MALEŠICE ČERNOKOSTELECKÁ 270

CZECH REPUBLIC

INFORMATION BULLETIN No: M337A/25b M337AK/20b M337AK.1/19b

Relates to : Motor oil pressure and engine speed at ground idle of the M 337A, M 337AK and M 337AK.1 engines operated on the Z 43 and Z 142 aircraft of all versions.

Reason : In summer months at temperatures higher than 30° C, the pressure of motor oil at the ground idle occurs sometimes to be lower than 120 kPa.

Measures: For operation of above mentioned engines installed into the Z 43 and Z 142 aircraft of all versions, the idle speed of ground idle is permitted to be 650 1/min. at maximum and motor oil pressure to be 100 kPa at minimum.

Expenses : No expenses arise.

Effectiveness On the date of issue.

**At Prague,
date:** 16.06. 2003

Ing. Josef PIETRIK
Quality Control Deputy

LOM PRAHA s.p

Ing. Miroslav BARNET
Director of LPM Division

LOM PRAHA s.p.