



LOM PRAHA
s.p.

TISKAŘSKÁ 8, 100 38 PRAHA 10, CZECH REPUBLIC

SERVICE LETTER No.:

0011/2009

Applicability: List of new documents issued during May and June 2009. It is from last revision of list of bulletins in January 23, 2008.

Reason : Information for users. The single lists of bulletins for inline engines will be revise at a later date.

Action: The following documents have been issued in above-mentioned term:

1. **Mandatory bulletin M462RF/51a** - Change of the lifetime of M462RF aircraft engines from current 4000 flight hours to unlimited lifetime. Only the total lifetime of the main connecting rod remains limited to 3500+50 hours.
2. **Mandatory bulletin LOM-MB-01a/2009** - The marking and use of the cut-down cylinder heads for M132, M332, M137, M337 engines of all models and versions. The heads are marked S1 or S2.
3. **Mandatory bulletin LOM-MB-02a/2009** - Possibilities of extending the calendar operating periods for the piston engines of model lines M332, M337, M137, M132 of all versions.
4. **Service letter 0009 /2009** - Announcement of persons authorized by LOM PRAHA s.p. to prolong the operational limits of the M337, M332, M137, M132 engines of all models and versions.
5. **Service letter 0010 / 2009** – Information on the LOM ASSISTANCE system cancellation.
6. **Service letter 0011 /2009** – List of new documents (this one).

Validity : As of the date of approval.

In Prague: June 22, 2009 Approved under the authority of the DOA No.: EASA.21J.306.

Approved by:

Jaroslav Böhm, in his own hand
Designing Department Manager