



LOM PRAHA
s.p.



SERVICE LETTER

#

0003/2005

- Scope:* M337A, AK engine users and organizations authorized to servicing/maintenance in compliance with the instructions CAST-145
- Justification:* Invalidation of M337A/9b and M337AK/4b bulletins.
- Provisions:* The M337A/9b and M337AK/4b bulletins issued on 15/07/1991 out of force. The provisions of these bulletins were introduced in the “Technical description and operation manual for the M 337A/AK, M 332A/AK, M 137A/AZ, M 132A/AK engines” issued by the type certificate holder LOM PRAHA s.p. as of 01/01/1998.
For the reason mentioned above the aforementioned bulletins validity are no more justifiable.
- Cost:* not applicable
- Validity:* on the date of publication
- Given in Prague on* 30/03/2005
- Developed by:* Ing. Jan Konarik
- Approved by:* Ing. Pavel Panek; Designing organization manager